

ZF 5HP19FL

Page 2: Flare on all gears, no transmission faults indicated on scan tool

Automatic Choice



Automatic Choice Ltd.
Unit 1A Farrington Fields
Farrington Gurney
Bristol
BS39 6UU
United Kingdom
Telephone: +44 (0)1761 452255
Fax: +44 (0)1761 453049
e-mail: info@automaticchoice.com

Automatic Choice Europe B.V.
De Schutterij 19
3905 PJ V eenendaal
The Netherlands
Telephone: +31 (0)318 590 591
Fax: +31 (0)318 590 177
e-mail: ace@automaticchoice.com

Automatic Choice S.L.
C/Moscatel 11
Pol. Ind. Arroyo De La Miel
Benalmádena
29631 Málaga
España
Telephone: +34 902 503 277
Fax: +34 952 440 798
e-mail: acexxi@acexxi.com

Automatic Choice EOOD
23, Nikolay Haytov Street
Floor 1 Office 4
1172 Sofia
Bulgaria
Telephone: +359 2 969 8609
Fax: +359 2 963 4565
e-mail: stelliana@automaticchoice.com

TECHNICAL INFORMATION BULLETIN

5HP19FL

Problem:

Flare on all gears, no transmission faults indicated on scan tool

Possible Cause:

Scan for engine faults, could come up with fault code T1626 "Engine signal fault, Brake Pedal Switch", could be fault on ABS sensors inside rear wheel.