

# Mercedes 722.5

---

**Page 2:** No forth gear; changes 1-2-3-5 missing out 4th gear, sometimes this can be confused as no 5th gear.



---

## TECHNICAL INFORMATION BULLETIN

# Merc 722.500

### *Problem:*

No forth gear; changes 1-2-3-5 missing out 4th gear, sometimes this can be confused as no 5th gear.

### *Cause:*

Computer is in default, and must be reset at Mercedes dealer. Once a fault has been detected, even if corrected, the computer remains in default unless reset.

### *Information:*

In default all power is cut to the solenoid, as power has to be applied to obtain 4th gear it is no longer available and will shift directly from 3rd to 5th.